

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BF505
SE
1/2-1
0.783 mi.
4132 ft.
LENNOX INDUSTRIAL PARK
384 N. MIDLER AVE
SYRACUSE, NY 13206
Site 13 of 15 in cluster BF

NY UST
NY AST
U003078217
N/A

Relative:
Higher
Actual:
419 ft.

UST:
Id/Status: 7-496286 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 7
Expiration Date: N/A
UTM X: 410044.34061
UTM Y: 4769823.20003
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 46322
Affiliation Type: Facility Owner
Company Name: NORTHEAST MANAGEMENT SERVICES, INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: P.O. BOX 1238
Address2: Not reported
City: CICERO
State: NY
Zip Code: 13039
Country Code: 001
Phone: (315) 437-8878
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 46322
Affiliation Type: Mail Contact
Company Name: NORTHEAST MANAGEMENT SERVICES, INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: P.O. BOX 1238
Address2: Not reported
City: CICERO
State: NY
Zip Code: 13039
Country Code: 001
Phone: (315) 437-8878
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 46322
Affiliation Type: Facility Operator
Company Name: LENNOX INDUSTRIAL PARK
Contact Type: Not reported
Contact Name: NORTHEAST MGMT. SERVICES, INC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Zip Code: Not reported
Country Code: 001
Phone: (315) 437-8878
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 46322
Affiliation Type: Emergency Contact
Company Name: NORTHEAST MANAGEMENT SERVICES, INC.
Contact Type: Not reported
Contact Name: FLORINE BASILE, PRES.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 471-5344
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 133534
Tank Status: Temporarily Out of Service
Material Name: Temporarily Out of Service
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AST:

Region: STATE
DEC Region: 7
Site Status: Unregulated/Closed
Facility Id: 7-496286
Program Type: PBS
UTM X: 410044.34061
UTM Y: 4769823.20003
Expiration Date: N/A
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id: 46322
Affiliation Type: Facility Owner
Company Name: NORTHEAST MANAGEMENT SERVICES, INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: P.O. BOX 1238
Address2: Not reported
City: CICERO
State: NY
Zip Code: 13039
Country Code: 001
Phone: (315) 437-8878
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 46322
Affiliation Type: Mail Contact
Company Name: NORTHEAST MANAGEMENT SERVICES, INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: P.O. BOX 1238
Address2: Not reported
City: CICERO
State: NY
Zip Code: 13039
Country Code: 001
Phone: (315) 437-8878
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 46322
Affiliation Type: Facility Operator
Company Name: LENNOX INDUSTRIAL PARK
Contact Type: Not reported
Contact Name: NORTHEAST MGMT. SERVICES, INC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 437-8878
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 46322
Affiliation Type: Emergency Contact
Company Name: NORTHEAST MANAGEMENT SERVICES, INC.
Contact Type: Not reported
Contact Name: FLORINE BASILE, PRES.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 471-5344
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 002
Tank Id: 133535
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/01/1992
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BF501
SE
1/2-1
0.780 mi.
4119 ft.

C & H AUTOMOTIVE
382 NORTH MIDLER AVENUE
SYRACUSE, NY

NY Spills **S104651634**
N/A

Site 9 of 15 in cluster BF

Relative:
Higher

Actual:
419 ft.

SPILLS:

Spill Number/Closed Date: 0060002 / 2000-05-10
Facility ID: 0060002
Facility Type: ER
DER Facility ID: 234798
Site ID: 289985
DEC Region: 7
Spill Cause: Deliberate
Spill Class: D4
SWIS: 3415
Spill Date: 2000-04-06
Investigator: CXROSSI
Referred To: Not reported
Reported to Dept: 2000-04-06
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-04-06
Spill Record Last Update: 2000-05-10
Spiller Name: LEE HERZOG
Spiller Company: C & H AUTOMOTIVE
Spiller Address: 382 NORTH MIDLER AVE
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks:

CTR ECO HEAD INVESTIGATED AND DETERMINED NO FURTHER ACTION WARRENTED
AFTERM CLEAN UP WAS PERFORMED."
"AS SHE WAS DRIVING BY SHE NOTICED SOMEONE COME OUT OF THE GARAGE AND
DUMP OIL ONTO THE GROUND FROM A CRANK CASE PART OF A CAR. ALSO SHE
STATED THAT THERE IS A PUDDLE OF ANTI FREEZE ON THE GROUND ALSO."

All Materials:

Site ID: 289985
Operable Unit ID: 836835
Operable Unit: 01
Material ID: 541178
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BF500
SE
1/2-1
0.780 mi.
4119 ft.

FRANKIE'S REPAIR SERVICE
382 N. MIDLER AVENUE
SYRACUSE, NY

NY RGA LF **S114956989**
N/A

Site 8 of 15 in cluster BF

Relative:
Higher

RGA LF:

Actual:
419 ft.

2012	FRANKIE'S REPAIR SERVICE	382 N. MIDLER AVENUE
2011	FRANKIE'S REPAIR SERVICE	382 N. MIDLER AVENUE
2010	FRANKIE'S REPAIR SERVICE	382 N. MIDLER AVENUE
2009	FRANKIE'S REPAIR SERVICE	382 N. MIDLER AVENUE
2008	FRANKIE'S REPAIR SERVICE	382 N. MIDLER AVENUE
2007	FRANKIE'S REPAIR SERVICE	382 N. MIDLER AVENUE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BF502
SE
1/2-1
0.780 mi.
4119 ft.

FRANKIE'S REPAIR SERVICE
382 N. MIDLER AVENUE
SYRACUSE, NY 13206

Site 10 of 15 in cluster BF

NY SWF/LF

S108468162
N/A

Relative:
Higher

SWF/LF:

Actual:
419 ft.

Flag: INACTIVE
Region Code: 7
Phone Number: 3154918043
Owner Name: Frank Sindoni
Owner Type: Private
Owner Address: 320 Wadsworth St.
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13208
Owner Email: Not reported
Owner Phone: 3154918043
Contact Name: Not reported
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: z Retired - Vehicle Dismantling Facility
Activity Number: Not reported
Active: No
East Coordinate: Not reported
North Coordinate: Not reported
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Last Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BF503
SE
1/2-1
0.783 mi.
4132 ft.

NORTH TOWING
384 N. MIDLER AVENUE
SYRACUSE, NY
Site 11 of 15 in cluster BF

NY RGA LF **S114959656**
N/A

Relative:
Higher

RGA LF:

Actual:
419 ft.

2012	NORTH TOWING	384 N. MIDLER AVENUE
2011	NORTH TOWING	384 N. MIDLER AVENUE
2010	NORTH TOWING	384 N. MIDLER AVENUE
2009	NORTH TOWING	384 N. MIDLER AVENUE
2008	NORTH TOWING	384 N. MIDLER AVENUE
2007	NORTH TOWING	384 N. MIDLER AVENUE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BF504
SE
1/2-1
0.783 mi.
4132 ft.
ABANDONED DRUMS
384 NORTH MIDLER AVENUE
EAST SYRACUSE, NY
Site 12 of 15 in cluster BF

NY Spills **S102122391**
N/A

Relative:
Higher
Actual:
419 ft.

SPILLS:

Spill Number/Closed Date: 9101884 / 1991-05-16
Facility ID: 9101884
Facility Type: ER
DER Facility ID: 232034
Site ID: 286289
DEC Region: 7
Spill Cause: Abandoned Drums
Spill Class: E6
SWIS: 3400
Spill Date: 1991-05-16
Investigator: GREGG
Referred To: Not reported
Reported to Dept: 1991-05-16
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Citizen
Cleanup Ceased: 1991-05-16
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1991-05-16
Spill Record Last Update: 1993-01-11
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
TG "
Remarks: "THREE 55 GALLON DRUMS; THREE 30 GALLON DRUMS. COMPLAINT GIVEN TO
MIKE MCPECK OF DHSR."

All Materials:

Site ID: 286289
Operable Unit ID: 955455
Operable Unit: 01
Material ID: 424419
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BF506
SE
1/2-1
0.783 mi.
4132 ft.
NORTH TOWING
384 N. MIDLER AVENUE
SYRACUSE, NY 13206
Site 14 of 15 in cluster BF

NY SWF/LF
S108468256
N/A

Relative:
Higher

SWF/LF:

Actual:
419 ft.

Flag: INACTIVE
Region Code: 7
Phone Number: Not reported
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: Not reported
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: z Retired - Vehicle Dismantling Facility
Activity Number: Not reported
Active: No
East Coordinate: Not reported
North Coordinate: Not reported
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Last Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BN507
SE
1/2-1
0.783 mi.
4133 ft.
Site 1 of 4 in cluster BN

FINDS **1016323882**
N/A

Relative:
Higher

FINDS:

Actual:
419 ft.

Registry ID: 110019514578

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BN508
SE
1/2-1
0.783 mi.
4133 ft.

PLUNKETT-WEBSTER INC
401 NORTH MIDLER
DEWITT, NY 13214

Site 2 of 4 in cluster BN

FINDS **1007804343**
ECHO **N/A**

Relative:
Higher

FINDS:

Actual:
419 ft.

Registry ID:

110019668698

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:

1007804343

Registry ID:

110019668698

DFR URL:

<http://echo.epa.gov/detailed-facility-report?fid=110019668698>

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BN509
SE
1/2-1
0.783 mi.
4133 ft.

PLUNKETT-WEBSTER INC - PARK SITE
401 N MIDLER AVE
SYRACUSE, NY 13206

Site 3 of 4 in cluster BN

RCRA-CESQG
NY Spills
NY MANIFEST

1004761472
NYR000087213

Relative:
Higher

RCRA-CESQG:

Actual:
419 ft.

Date form received by agency: 01/01/2007
Facility name: PLUNKETT-WEBSTER INC - PARK SITE
Facility address: 401 N MIDLER AVE
SYRACUSE, NY 13206
EPA ID: NYR000087213
Mailing address: N MIDLER AVE
SYRACUSE, NY 13206
Contact: PAUL HAANSCHOTEN
Contact address: N MIDLER AVE
SYRACUSE, NY 13206
Contact country: US
Contact telephone: 315-463-5236
Contact email: PHANNSCHOTEN@PARKSITE.COM
EPA Region: 02
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: PAUL HAANSCHOTEN
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/01/2004
Owner/Op end date: Not reported

Owner/operator name: PLUNKETT-WEBSTER INC
Owner/operator address: 2 CLINTON PL
NEW ROCHELLE, NY 10801
Owner/operator country: Not reported
Owner/operator telephone: 914-636-8770
Owner/operator email: Not reported
Owner/operator fax: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PLUNKETT-WEBSTER INC
Owner/operator address: 2 CLINTON PL
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-636-8770
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/01/2004
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: PLUNKETT-WEBSTER INC - PARK SITE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 11/02/2004
Site name: PLUNKETT-WEBSTER INC - PARK SITE
Classification: Small Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 06/15/2000
Site name: PLUNKETT-WEBSTER INC
Classification: Small Quantity Generator

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 05/17/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

SPILLS:

Spill Number/Closed Date: 9908875 / 2002-08-05
Facility ID: 9908875
Facility Type: ER
DER Facility ID: 106200
Site ID: 122497
DEC Region: 7
Spill Cause: Unknown
Spill Class: C3
SWIS: 3415
Spill Date: 1999-10-21
Investigator: CFMANNES
Referred To: Not reported
Reported to Dept: 1999-10-21
CID: 257
Water Affected: Not reported
Spill Source: Unknown

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-10-21
Spill Record Last Update: 2002-08-05
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: REBERTA GORDON
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
CM LIMITED INFORMATION PROVIDED. "

Remarks: "during soil borings they found a sheen in the ground water and ther
borings are on the property boarder and there is a old gas station
there - "

All Materials:

Site ID: 122497
Operable Unit ID: 1087566
Operable Unit: 01
Material ID: 297977
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:

Country: USA
EPA ID: NYR000087213

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Facility Status: Not reported
Location Address 1: 401 N MIDLER AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: SYRACUSE
Location State: NY
Location Zip: 13206
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYR000087213
Mailing Name: PLUNKETT WEBSTER
Mailing Contact: PAUL HAANSOKOTEN
Mailing Address 1: 401 N MIDLER AVE
Mailing Address 2: Not reported
Mailing City: SYRACUSE
Mailing State: NY
Mailing Zip: 13206
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3154635236

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2008
Trans1 State ID: NYD013277454
Trans2 State ID: Not reported
Generator Ship Date: 03/12/2008
Trans1 Recv Date: 03/12/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/12/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000087213
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD013277454
TSDF ID 2: Not reported
Manifest Tracking Number: 003595778JJJ
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Quantity: 200.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Waste Code: D001
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

[Click this hyperlink](#) while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BN510
SE
1/2-1
0.783 mi.
4133 ft.
PARKSITE-PLINKETT & WEBSTER
401 NORTH MIDLER AVENUE
SYRACUSE, NY 13206
Site 4 of 4 in cluster BN

NJ MANIFEST
S107610185
N/A

Relative:
Higher

Actual:
419 ft.

NJ MANIFEST:
EPA Id: NYR000847213
Mail Address: 401 NORTH MIDLER AVENUE
Mail City/State/Zip: SYRACUSE 13206
Facility Phone: 3154635236
Emergency Phone: Not reported
Contact: PAT TOOMBS
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: NJA5210432
EPA ID: NYR000847213
Date Shipped: 11/30/2004
TSDF EPA ID: NJD002200046
Transporter EPA ID: VTR000500090
Transporter 2 EPA ID: VTR000500090
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 11/30/2004
Date Trans2 Transported Waste: 12/01/2004
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 12/10/2004
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	02030521
Was Load Rejected:	SYRACUSE 13206
Reason Load Was Rejected:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BF512
SE
1/2-1
0.785 mi.
4146 ft.

SUPERIOR PLATING
386 N MIDLER AVE
SYRACUSE, NY 13206

Site 15 of 15 in cluster BF

RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

1001233154
NYR000062711

Relative:
Higher

RCRA NonGen / NLR:

Actual:
419 ft.

Date form received by agency: 01/01/2007
Facility name: SUPERIOR PLATING
Facility address: 386 N MIDLER AVE
SYRACUSE, NY 13206
EPA ID: NYR000062711
Mailing address: COUNTY RTE 12
PENNELLVILLE, NY 13132
Contact: BETTY BUCHER
Contact address: COUNTY RTE 12
PENNELLVILLE, NY 13132
Contact country: US
Contact telephone: 315-676-1031
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: BETTY BUCHER
Owner/operator address: 1153 COUNTY RTE 12
PENNELLVILLE, NY 13132
Owner/operator country: US
Owner/operator telephone: 315-676-1031
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BETTY BUCHER
Owner/operator address: 1153 COUNTY RTE 12
PENNELLVILLE, NY 13132
Owner/operator country: US
Owner/operator telephone: 315-676-1031
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: SUPERIOR PLATING
Classification: Not a generator, verified

Date form received by agency: 10/27/1998
Site name: SUPERIOR PLATING
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 01/04/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004548197

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1001233154
Registry ID: 110004548197
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004548197>

NY MANIFEST:

Country: USA
EPA ID: NYR000062711
Facility Status: Not reported
Location Address 1: 386 N MIDLER AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: SYRACUSE
Location State: NY
Location Zip: 13206
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYR000062711
Mailing Name: SUPERIOR PLATING
Mailing Contact: ELIZABETH BUCHER
Mailing Address 1: 1153 CTY RT 12
Mailing Address 2: Not reported
Mailing City: PENNELLVILLE
Mailing State: NY
Mailing Zip: 13132
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3156761031

NY MANIFEST:

Document ID: NYG0510804
Manifest Status: Not reported
seq: 01
Year: 1999
Trans1 State ID: NYPZ5055
Trans2 State ID: Not reported
Generator Ship Date: 02/15/1999
Trans1 Recv Date: 02/15/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/15/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000062711
Trans1 EPA ID: NYD986980753

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Trans2 EPA ID:	Not reported
TSD ID 1:	NYD049836679
TSD ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00181
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	01.00

[Click this hyperlink](#) while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BK532
SE
1/2-1
0.790 mi.
4172 ft.

EASTWOOD LUMBER
401 MIDLER AVE
SYRACUSE, NY

NY LTANKS

S105997122
N/A

Site 2 of 9 in cluster BK

Relative:
Higher

Actual:
418 ft.

LTANKS:

Spill Number/Closed Date: 0207741 / 2002-10-26
Facility ID: 0207741
Site ID: 247484
Spill Date: 2002-10-25
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 3415
Investigator: BFMATTHE
Referred To: Not reported
Reported to Dept: 2002-10-25
CID: 398
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-10-25
Spill Record Last Update: 2003-01-22
Spiller Name: SAME
Spiller Company: MOHAWK VALLEY OIL
Spiller Address: 212 NORTH LAKE STREET
Spiller County: 001
Spiller Contact: DOUG
Spiller Phone: (315) 463-5236
Spiller Extention: Not reported
DEC Region: 7
DER Facility ID: 203209
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
BM INSPECTION OF AREA SHOWS CLEANUP COMPLETE."
Remarks: "overfill and clean up in progress. no call back needed."

All Materials:

Site ID: 247484
Operable Unit ID: 860583
Operable Unit: 01
Material ID: 514750
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BK537
SE
1/2-1
0.795 mi.
4195 ft.
SPRINT SYRACUSE NY POP
402 NORTH MIDLER AVE
SYRACUSE, NY 13206
Site 3 of 9 in cluster BK

NY TANKS **S116349616**
N/A

Relative:
Higher

Actual:
420 ft.

TANKS:

Facility Id: 7-600791
Region: STATE
DEC Region: 7
Site Status: Active
Program Type: PBS
Expiration Date: 04/04/2021
UTM X: 410467.40124
UTM Y: 4769767.70095

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BK538
SE
1/2-1
0.795 mi.
4195 ft.

SPRINT - SYRACUSE
402 N MIDLER AVE
SYRACUSE, NY 13206

Site 4 of 9 in cluster BK

Relative:
Higher

FINDS:

Actual:
420 ft.

Registry ID: 110041683657

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

FINDS **1014820685**
N/A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BK554
SE
1/2-1
0.810 mi.
4278 ft.
JAN NASTRI MIDLER PROPERTY
404 NORTH MIDLER AVE
DEWITT, NY 13214
Site 6 of 9 in cluster BK

NY Spills **S117852497**
N/A

Relative:
Higher

Actual:
406 ft.

SPILLS:

Spill Number/Closed Date: 1500862 / 2015-07-14
Facility ID: 1500862
Facility Type: ER
DER Facility ID: 461793
Site ID: 507035
DEC Region: 7
Spill Cause: Deliberate
Spill Class: B3
SWIS: 3426
Spill Date: 2015-04-18
Investigator: KCKEMP
Referred To: Not reported
Reported to Dept: 2015-04-24
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: DEC
Cleanup Ceased: 2015-07-14
Cleanup Meets Std: False
Last Inspection: 2015-04-20
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2015-04-24
Spill Record Last Update: 2015-07-14
Spiller Name: JAN NASTRI
Spiller Company: NASTRI REAL ESTATE
Spiller Address: 2501 JAMES ST - STE 100
Spiller Company: 999
Contact Name: JAN NASTRI
DEC Memo: "4/24/2015 - VISITED SITE WITH NASTRI AND CONSULTANT, ECO YACAVONE TO WITNESS LOCATION WHERE TANK AND SOILS REMOVED FROM 832 NORTH STATE ST ON 4/18/2015 WERE STORED PENDING DISPOSAL (SPILL 1500713). SIGNIFICANT STAINING NOTED UNDER 500 GALLON TANK THAT HAD NOT BEEN CLEANED, AND HAD SEVERAL HOLES AND SAWCUTS WHERE NASTRI REPORTEDLY DRAIN TANK LIQUIDS FROM. ALSO, APPROX 40 CY OF SOIL REMOVED FROM 832 NORTH STATE ST WAS OBSERVED AT THIS LOCATION ON BARE GROUND, BUT COVERED BY TARPS (SEE PHOTOS). NASTRI TO WORK WITH BENJAMIN HAITH, PG, OF GZA GEOENVIRONMENTAL TO REMEDIATE THIS PROPERTY ALONG WITH 832 NORTH STATE ST SPILL 1500713. PHOTOS TO BE DECDOD'D ONCE FILES CREATED, AND RESPONSIBILITY LETTER AND STIP TO BE SENT FOR THIS SITE. NASTRI IS BEING REPRESENTED BY HISCOCK BARCLAY. KCKEMP 6/24/2015 - Tank, soil, and areas beneath tank and soils excavated and removed from site by Nastri / Lift Safe Fuel Safe. Material transported by Ricelli to Seneca Meadows LF for disposal. End point samples taken. LSFS to report analytical to DEC. KCKemp 7/14/2015 - Closure report

Remarks: received and filed. Spill closed."

"SEE DEC COMMENTS"

All Materials:

Site ID: 507035
Operable Unit ID: 1256371
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material ID:	2259251
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ZJ5270
SW
> 1
2.910 mi.
15364 ft.

MIDLER & CANAL #2
MIDLER AVE
SYRACUSE, NY

Site 12 of 17 in cluster ZJ

NY Spills **S102164560**
N/A

Relative:
Lower

Actual:
371 ft.

SPILLS:

Spill Number/Closed Date: 9002893 / 1992-01-13
Facility ID: 9002893
Facility Type: ER
DER Facility ID: 282076
Site ID: 120702
DEC Region: 7
Spill Cause: Deliberate
Spill Class: Not reported
SWIS: 3400
Spill Date: 1990-05-07
Investigator: HDWARNER
Referred To: Not reported
Reported to Dept: 1990-05-07
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: DEC
Cleanup Ceased: 1990-06-07
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1990-07-01
Spill Record Last Update: 1992-07-08
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
HW 03/18/91: SOURCE OF ACCUMULATED PETROLEUM COULD NOT BE TRACED TO
ITS ORIGINS. DISCHARGE IS IN ISOLATED AREA AND MAY HAVE OCCURED
SEVERAL YRS PRIOR TO DISCOVERY. "
Remarks: "SEVERAL HUNDRED GALLONS OF PETROLEUM ACCUMULATED ON SURFACE WATER."

All Materials:

Site ID: 120702
Operable Unit ID: 940789
Operable Unit: 01
Material ID: 437618
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BT563
SE
1/2-1
0.817 mi.
4312 ft.
QUICKWAY #11
356 NORTH MIDLER AVE
SYRACUSE, NY 13206
Site 1 of 2 in cluster BT

NY UST
U004107623
N/A

Relative:
Higher

UST:

Actual:
426 ft.

Id/Status: 7-600836 / Active
Program Type: PBS
Region: STATE
DEC Region: 7
Expiration Date: 01/07/2022
UTM X: 410017.96449
UTM Y: 4769836.47145
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 47272
Affiliation Type: Facility Owner
Company Name: JAN F NASTRI & ROBERT C ABBOTT JR
Contact Type: DIRECTOR - FACILITIES COMPLIANCE SAFETY
Contact Name: RUSSELL WARK
Address1: 2501 JAMES ST
Address2: Not reported
City: SYRACUSE
State: NY
Zip Code: 13206
Country Code: 001
Phone: (315) 437-1037
EMail: Not reported
Fax Number: Not reported
Modified By: KCKEMP
Date Last Modified: 2017-01-11

Site Id: 47272
Affiliation Type: Mail Contact
Company Name: MIRABITO FUEL GROUP
Contact Type: Not reported
Contact Name: RUSSELL WARK
Address1: 49 COURT ST, THE METROCENTER
Address2: PO BOX 5306
City: BINGHAMTON
State: NY
Zip Code: 13902
Country Code: 001
Phone: (607) 352-2953
EMail: RUSSELL.WARK@MIRABITO.COM
Fax Number: Not reported
Modified By: KCKEMP
Date Last Modified: 2011-03-31

Site Id: 47272
Affiliation Type: Facility Operator
Company Name: QUICKWAY #11
Contact Type: Not reported
Contact Name: MATT SCHYNDLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Zip Code: Not reported
Country Code: 001
Phone: (315) 432-0152
EMail: Not reported
Fax Number: Not reported
Modified By: KCKEMP
Date Last Modified: 2017-08-02

Site Id: 47272
Affiliation Type: Emergency Contact
Company Name: JAN F NASTRI & ROBERT C ABBOTT JR
Contact Type: Not reported
Contact Name: MATT SCHYNDLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (607) 237-9296
EMail: Not reported
Fax Number: Not reported
Modified By: KCKEMP
Date Last Modified: 2017-08-02

Tank Info:

Tank Number: 1A
Tank ID: 139941
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 15000
Install Date: 08/01/1996
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KCKEMP
Last Modified: 04/14/2017

Equipment Records:

D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I01 - Overfill - Float Vent Valve
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

Tank Number: 1B
Tank ID: 216918
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 5000
Install Date: 08/01/1996
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KCKEMP
Last Modified: 04/14/2017

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

ZJ5271
SW
> 1
2.910 mi.
15364 ft.

MIDLER AVE.
MIDLER AVE
SYRACUSE, NY

Site 13 of 17 in cluster ZJ

NY Spills S102165754
N/A

Relative:
Lower

Actual:
371 ft.

SPILLS:

Spill Number/Closed Date: 8603796 / 1989-02-10
Facility ID: 8603796
Facility Type: ER
DER Facility ID: 285686
Site ID: 242750
DEC Region: 7
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 3415
Spill Date: 1986-09-10
Investigator: HDWARNER
Referred To: Not reported
Reported to Dept: 1986-09-10
CID: Not reported
Water Affected: 12
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: 1986-10-10
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: True
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1986-09-11
Spill Record Last Update: 1989-03-17
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks:

HW 10/10/86: ALLWASH HIRED TO CLEANUP. SAMPLE OF OIL BY UPSTATE LAB INDICATED NON PCB. 03/10/88: TRANSFORMER ON SUTTON INVESTING CORP. PROPERTY FELL OVER SPILLING APPROX. 75 GALLONS OF NON-PCB OIL. " "NYS CONST. MGT. AT THIS SITE CONTACTED DEC TO SAY THAT A LOT OF OIL IS COMING OUT OF 36 RCP. BRIDGE IN THAT AREA IS BEING REMOVED.-CONSIDERED UNCOLLECTIBLE PER ATTORNEY GENERAL'S OFFICE."

All Materials:

Site ID: 242750
Operable Unit ID: 900665
Operable Unit: 01
Material ID: 476611
Material Code: 0016A
Material Name: non PCB oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 75.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material ID:	2259251
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

ZJ5272
SW
> 1
2.910 mi.
15364 ft.

TANK REMOVAL
MIDLER AVE
SYRACUSE, NY

Site 14 of 17 in cluster ZJ

NY Spills **S104194934**
N/A

Relative:
Lower

Actual:
371 ft.

SPILLS:

Spill Number/Closed Date: 9960034 / 2002-08-05
Facility ID: 9960034
Facility Type: ER
DER Facility ID: 282076
Site ID: 120703
DEC Region: 7
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 3400
Spill Date: 1993-10-18
Investigator: CFMANNES
Referred To: Not reported
Reported to Dept: 1993-10-18
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: 1993-10-18
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1999-09-10
Spill Record Last Update: 2002-08-05
Spiller Name: KIM GOODRICH
Spiller Company: GEORGIA -PACIFIC CORP.
Spiller Address: MIDLER AVE
Spiller Company: 001
Contact Name: KIM
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
CM DISPOSAL RECEIPTS AND LAB DATA NOT SUBMITTED TO DEC"
Remarks: "TANK REMOVAL, 125 YD3 SOIL REMOVED"

All Materials:

Site ID: 120703
Operable Unit ID: 1093186
Operable Unit: 01
Material ID: 290552
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported